





## R Class



Loading Holes

560

520




BOLTS: 12 Bolts (M16)



De-airation Holes

350

314



BOLTS: 8 Bolts (M16)